

#### **PUBLIC SUMMARY REPORT**

#### TRACEABILITY TO PLANTATION ASSESSMENT

Name of Parent Company: Hock Huat Sdn. Bhd

Name of Palm Oil Mill: Kluang Oil Palm Processing Sdn. Bhd.


Mill MPOB License No.: 500008704000

Mill Address: Bt. 4 ½, Jln.Mersing, 86000 Kluang, Johor. GPS Coordinate of Palm Oil Mill: 2.05869, 103.36158

Supplied Mewah's Refineries: Mewaholeo Industries Sdn Bhd (Pasir Gudang)

**Assessment Date:** 18<sup>th</sup> Aug 2017 (Friday)

# A. Fresh Fruit Bunch (FFB) Traceability:



FFB Sources	Traceability Score	Overall TTP Score %	
Own Plantations/ Estates	Not Applicable		
3 <sup>rd</sup> Party Plantations/ Estates	100%	1000/	
Dealers	100%	100%	
Smallholders	100%		



# B. Environmental Risk Analysis

- 1. Environmental risk assessment is carried out within theoretical FFB catchment area (50km radius) in Kluang Oil Palm Processing Sdn. Bhd. using Global Forest Watch (GFW) tool.
- 2. The overall environmental risk ranking of Kluang Oil Palm Processing Sdn. Bhd. is summarized as follows.

Potential Environmental Risk Factors							
D 4 6	Tree	Potential	TD.	Tree	Tree		
Rate of Tree	Cover Loss on	Future Loss in	Tree Cover Loss	Cover Loss on	Cover Loss on Carbon	Fire	
Cover Loss	Primary	Primary	on Peat	Protected	Dense	Activity	
	Forest	Forest		Area	Area		
Medium	Low	Low	Medium	Medium	Medium	Medium	

The following mapping is used as an indicator to indicate the potential environmental risks of the assessed palm oil mill.

Leger	nd	
	Malaysia peatlands (2004)	52 Bekok
	Protected areas (2018)	
	-Strict nature reserve	déhaah
	Protected areas (2018)	
	-Habitat and species management area	Kahan
	Protected areas (2018)	
	-Protected landscape or seascape	
	Protected areas (2018) -Not reported	
	Tree cover loss (2015-2018)	
	Intact Forest Landscapes (2000-2016)	
	Intact Forest Landscapes	Kluang
	-Reduction in extent 2000-2013	Yong Peng
	Intact Forest Landscapes	The street of the second of th
	-Reduction in extent 2013-2016	
	Deforestation alerts (GLAD) 2016 - Present	
	Palm oil mills (2018)	Ayer Hitam:
	Tree cover gain (2001-2012)	
	Fire Alert (VIIRS)	
#	Assessed Palm Oil Mill	Simpang



### C. Social Impact Assessment

- 1. We also carried out social impact assessment during the mill assessment.
- 2. The mill representatives were made to understand the important pillars of good social responsibility practices, mandatory compliance of national labour laws & human rights, and the needs to improve social engagement with local community.

The findings of the social impact assessment are outlines in the following table:

Respect of Workers & Local Community Right	No	
Compliance with Safety & Health	Yes	
Compliance with National Labour Laws and Regulations	Yes	
Compliance with Housing & Amenities Act 1990	Yes	
Respect of FPIC	Partial Compliance	
<b>CSR/Community Contribution</b>	Yes	
Availability of grievance mechanism	No	
Fair & Equitable Trading	Yes	

### Disclaimers:

The traceability to plantation assessment is carried out through observation, documentation reviews and interview based on Mewah's Sustainable Palm Oil Policy and Mewah's Supplier Assessment Guidelines. The above findings are collected through multiple sampling methodologies during the assessment date. The information contained in this report may contain confidential, proprietary, privileged and/or private information. It is only intended for the users of Mewah Group Sustainability Dashboard.